



LiteMat Spectrum Dimmer Software

New Firmware Version: 1.10

Release Date: 03/17/2020

Issue	Consequence	Estimated Correction Date
CCT may shift slightly when operating units at an extremely low output.	The output may appear slightly green at the low end. To correct, adjust the "tint" setting to suit needs.	3rd Quarter 2020

NOTES:

For more information, see <http://www.litegear.com/firmware> Be sure to read warnings and notices in the LiteMat Spectrum user's guide.