

**Spectrum OS Firmware - Version 2.8 (LiteDimmer Spectrum AC600)****Date:** 01/18/2023

Issue	Consequence	Estimated Completion Date
When switching between an ethernet protocol and CRMX, it is possible that the connected light may exhibit momentary abnormal output behavior.	When this occurs, the light output may turn off for a moment and then turn back on. To mitigate this behavior, it is recommended to disconnect either the ethernet or CRMX protocol before activating the other.	<b>Early Q3 2023</b>

**NOTES:**

- Visit [www.litegear.com](http://www.litegear.com) for latest firmware.